



Div of The Crane Industry Council of Australia ABN 73 002 565 773

ARTICULATED MOBILE CRANE

Annual Report

Company	C & C Construction Services	ABN	82 780 055 822
Address	1 Sir Henry Parkes Avenue	Representative	Mr Peter Riters
MEDOWIE State Postcode	NSW 2318	Phone Email	0419 762 507 priters@cccs.net.au

Make		Franna		
Model		MAC 25		
Serial Number		25912		
Plant Number Year of Manufacture Design Registration Number Plant Registration Road Registration Max Load Number of Axles Lower Hours		114		
		2013 Q16799		
		756 TGR		
		25000		
		2		
		4926		
		Kilometers		25122
Country where	assessed	Australia	State	NSW
Operators Man	ual in English	Yes	Log Book	Yes
Crane Safety M	anual	No		
Assessed By	Troy Kiem		Company	A1 Crane Inspections
Reg. No.	NSW1082		Address	P O Box 414 KURRI KURRI
Phone	0425 384 09	1	State	NSW
Email	a1craneinspe	ections@gmail.com	Postcode	2327
Initital Inspection	on Date	04/09/2017	Issued Date	07/09/2017
Re-Inspection	Date	06/09/2017	Expiry Date	06/09/2018
Conforms to	Checklist	Yes		

This report is confirmation that the crane has undergone an annual inspection to the appropriate standard and is considered safe for continued operation at time of inspection.

Actions Required - NA

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

 $\ensuremath{\textcircled{\text{\scriptsize C}}}$ The Crane Industry Council of Australia 2009

BOOM AND ATTACHMENTS

Base Section No. 1 Section No. 2 Section No. 3 Section Length Markings Rope Compensation System Hook Lift Lugs and Tonnage Decals Head Sheaves and bearings Idler Sheave and Bearing Rooster Sheave and Bearing Extension / Fly Jib Mounts Machinery Hook Boom Lift Cylinders Lock Valve(s) Extension Cylinders Lock Valve(s) Extend Ropes / Chains Retract Ropes / Chains Boom Length Recoil Drum(s) Boom Angle Indicator Extension / Fly Jib Extension / Fly Jib Extension Sheaves and Bearings	OK OK OK N/A N/A N/A OK OK OK OK OK OK OK OK OK OK OK OK - Not visible. OK OK OK OK OK OK OK N/A N/A
Boom Head	OK
Rooster Sheave	N/A
Extension / Fly	N/A
HOOK BLOCKS - WITH CRANE Description Manufacturers Identification Safety Latches Sheaves and Bearings Swivel Branded WLL Branded WLL Branded with Weight (Tare) HOOK BLOCKS - WITH CRANE No. 2	1 x Block supplied. OK - BBT14749 N/A OK - 3 N/A OK - 25000kgs OK - 230kgs
Description	BT14378
Manufacturers Identification	OK - BTT14378
Safety Latches	OK
Sheaves and Bearings	N/A
Swivel	OK
Branded WLL	OK - 25t
Branded with Weight (Tare)	N/A

Additional Comments on Boom and Attachments All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

© The Crane Industry Council of Australia 2009

FRAME AND CABIN

Additional Comments on Frame and Cabin All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

DRIVE SYSTEMS

Additional Comments on Drive Systems All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports © The Crane Industry Council of Australia 2009

CHASSIS INSPECTION

Frames	OK
Suspension System	OK
Axle Lock Outs (if fitted)	OK
Steering Components - Lugs / Pins etc	OK
Front Axle(s)	OK
Rear Axle(s)	OK
Differentials / Planetary Drives	OK
Transfer Case	OK
Drive Lines	OK
ABS Brakes	N/A
Front Brake(s)	OK
Rear Brake(s)	OK
Holding / Parking Brake	OK
Emergency Brake Release	OK
Front Wheels and Tyres	OK
Rear Wheels and Tyres	OK
Spare Wheel	OK
Engine Cowls	OK
Tackle Boxes	OK
Slewing Ring / Articulation Joints	OK - Requires adjusting.
Fire Extinguisher	OK
-	

Additional Comments on Chassis Inspection All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

HYDRAULIC SYSTEM

Hydraulic Reservoir & Oil Level	OK
Return Filters and Housing	OK
Suction Lines and Hoses	OK
Oil Cooler(s)	OK
Main Pump(s)	OK
Steering Pump	OK
Emergency Steering Pump	REMEDIED - Not functioning.
Steering Cylinder	OK
Relief Valves	OK
Flow Control Valves	OK
Pressure Filter and Housing	OK

Additional Comments on Hydraulic System All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

 $\ensuremath{\textcircled{\text{\scriptsize C}}}$ The Crane Industry Council of Australia 2009

AIR SYSTEMS

Compressor	OK
Air Reservoirs	OK
Drain Valves	OK
Air Lines	OK
Brake Chambers	REMEDIED - Front axle air leaking with park brake released.
Brake Valves	OK
Air Cylinders	OK
Gauges	OK
Air Dryer	OK

Additional Comments on Air Systems All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

ELECTRICAL SYSTEMS

Battery Box	OK
Battery Cables	OK
Battery Isolator	OK
Head Lights	OK
Tail Lights	OK
Stop Lights	OK
Directional Indicators	OK
Hazard Lights	OK
Clearance Lights	OK
Back-up Alarm	OK
Switches and Relays	OK
Work Lights	OK
Horn for Road Travel	OK

Additional Comments on Electrical Systems All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

© The Crane Industry Council of Australia 2009

Load Chart Reference Number Printed Chart - No Load		CMN OK
	Printed Chart	Rated Capacity Indicator
Boom Angle, deg	55.00	54.60
Boom Length, m	18.42	18.40
Radius, m	8.00	8.00
Load, kg	4,800.00	4,800.00

Load Chart Reference Number Rated Load - Boom Fully Extended CMN OK

	Rated Capacity Indicator	Measured
Radius, m	15.20	15.10
Load, kg	1,900.00	1,445.00

Rated Load in Stability

OK

	Rated Capacity Indicator	Measured
Radius, m	15.20	15.10
Load, kg	1,900.00	1,445.00

Line Pull Test

	Rated Capacity Indicator	Measured
Load, kg	4,200.00	4,200.00

	Rated Capacity Indicator	Measured
Load, kg	4,200.00	4,200.00

Winch Condition & Oil Level Winch Rope Condition / Anchors Overload Warning Lights and Alarms OK - Oil level internal, service records should confirm.

OK - 14mm OEM supplied 110m OK

Additional Comments on Functional Tests - Main Winch

RCL and the RCI accuracy confirmed within acceptable tolerances. available test weights didn't exceed the lowest MRC. Accuracy of the RCL and load chart confirmed.

FUNCTIONAL TESTS - AUXILIARY WINCH - NA

CRACK INSPECTION

No Cracks Detected

OK - No NDT report found

Additional Comments on Crack Inspection Annual independent third party VISUAL inspection completed. Crack inspection carried out during and after the load testing. No visible or previously recorded cracks found.

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

$\ensuremath{\mathbb{C}}$ The Crane Industry Council of Australia 2009

All CraneSafe forms, checklists, surveys, audits and reports together with the embedded methodology contained within are the intellectual property of The Crane Industry Council of Australia and may not be use without The Crane Industry Council of Australia's prior written consent.

OK

OK

ADDITIONAL ANNUAL INSPECTIONS STIPULATED BY THE MANUFACTURER

Note

OK - Service History (Available). Log book-Pre/Start entries available (Located in the crane cabin: previously logged faults). This report is: Prepared for the date of inspection: Not confirming all global standards: Not a pre-purchase report. No responsibil

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports © The Crane Industry Council of Australia 2009

APPENDICES CRANE





Model

Serial Number


Lower Hours

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports © The Crane Industry Council of Australia 2009

ASSESSMENT





HYDRAULIC SYSTEM

Emergency Steering Pump

AIR SYSTEMS

Brake Chambers

Log Book New book installed. Original book stayed with last customer.


Maintenance Records

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

 $\ensuremath{\textcircled{\text{\scriptsize C}}}$ The Crane Industry Council of Australia 2009

FUNCTIONAL TESTS - MAIN WINCH







Load Chart Reference Number

Rated Load - Boom Fully Extended - Load RCI

Rated Load - Boom Fully Extended - Load Measured

Accredited for compliance with ISO/IEC 17020

NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration and inspection reports

 $\ensuremath{\textcircled{\text{\scriptsize C}}}$ The Crane Industry Council of Australia 2009



No. AC A 126149-4 PO Box 136 MOUNT WAVERLEY VIC 3149 P: +61 (03) 9501 0078 E: assessments@cranesafe.com.au

Div of The Crane Industry Council of Australia ABN 73 002 565 773

ARTICULATED MOBILE CRANE

Maintenance List

Company	C & C Construction Services
Address	1 Sir Henry Parkes Avenue
MEDOWIE State	NSW
Postcode	2318

Franna
MAC 25
25912
114
2013
Q16799
MC6-198063/16/0
756TGR
25000
2
4926
25122

Country where assessedAustraliaOperators Manual in EnglishYesCrane Safety ManualNo

Assessed By	Troy Kiem
Reg. No.	NSW1082
Phone	0425 384 091
Email	a1craneinspections@gmail.com

Initital Inspection Date Maximum Period Allowed Before Re-assessment Conforms to Checklist

ABN	82 780 055 822	
Representative	Mr Peter Riters	

Phone Email

0419762507 priters@cccs.net.au



State Log Book NSW Yes

CompanyA1 Crane InspectionsAddressP O Box 414 KURRI KURRIStateNSWPostcode2327

04/09/2017 ASAP. No more than 30 days **No**

© The Crane Industry Council of Australia 2009

HYDRAULIC SYSTEM

No. AC A 126149-4

Item Emergency Steering Pump

NOT OK - Not functioning.

Remedied By

Additional Comments on Hydraulic System All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

Emergency Steering Pump

AIR SYSTEMS

Item **Brake Chambers**

NOT OK - Front axle air leaking with park brake released.

Remedied By IROY

Additional Comments on Air Systems All items marked OK either functioned and/or appeared Satisfactory. No previously recorded faults.

Brake Chambers

ADDITIONAL ANNUAL INSPECTIONS STIPULATED BY THE MANUFACTURER

DEFECT CARAGO OUT BY MONTOR VALLEY PLANT.

MAINTENANCE

They maket is

© The Crane Industry Council of Australia 2009